

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0195029

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Merchant-B

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 26, T-22-S, R-34-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Phillips Petroleum Company

3. ADDRESS OF OPERATOR

Room B-2, Phillips Building, Odessa, Texas 79760

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FE, 1980' FS lines

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3432' Gr., 3449' RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Shut in for evaluation. ☐REPAIRING WELL ☐ALTERING CASING ☒ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

11-19-71: Howco spotted 200 sx Class H cement w/5/10% LWL through open end DP from 13570' to 12670'. Pulled 20 stands DP, circulated and conditioned hole for 2 hours. Spotted 50 sx Class H cement w/5/10% LWL from 11650' to 11450'. Hole loaded with mud-laden fluid between plugs. 11-20-71: Pulled DP, cleaned pits, removed BOP. Started rigging down rotary. Released Cactus Drilling Company at 1:00 P.M., 11-20-71.

Shut well in for evaluation.

This confirms our proposal and temporary abandonment on Form 9-331, dated November 19, 1971.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. J. Mueller

TITLE Senior Reservoir Engineer

DATE

11-30-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED

SEP 1 1971

OIL CONSERVATION COMM.
HOOLE, R. M.