

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLO
(Other instructions
reverse side)

TE
(10)

Form approved,
Budget Bureau No. 42-R1421.

3. LEASE DESIGNATION AND SERIAL NO.

LC-269048

4. LE INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. UNIT AGREEMENT NAME

6. NAME OF LEASE NAME

Elliott Federal

7. WELL NO.

#1

8. FIELD AND POOL, OR WILDCAT

Wantz Abo

9. SEC., T., R., M., OR BOX, AND
SURVEY OR AREA

Sec. 9, T-21-S, R-38-E

10. NAME OF OPERATOR

Hanson Oil Corporation

11. ADDRESS OF OPERATOR

P.O. Box 1515-Roswell, New Mexico 88201

12. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1650' ESL & 990' FWL

13. PERMIT NO.

14. ELEVATIONS (Show whether LS, ST, GR, etc.)

3568 G.L.

15. COUNTY OR PARISH

Lea

16. STATE

N.M.

19. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PERM OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was plugged as follows on 10-31-73

PLUG NO.	SACKS	DEPTH OF PLUG TO BOTTOM-TOP	REMARKS
1	5	CIBPC7336	
2	35	5535-5435	5-1/2" stub
3	35	4050-3950	8-5/8" shoe
4	65	1700-1600	
5	65	1223-1123	8-5/8" stub
6	65	360-260	13-3/8" shoe
7	10	SURFACE	

Hole was filled with mud between plugs. Casing Recovered: 5-1/2" 5560
8-5/8" 1220

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

VicePresident-Production

1-15-74

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

FEB 27 1974

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side