| NO. OT COMES RECEIVED | NEW MEXICO OIL CONSERVATION COMMISSION | Form C-103 Supersedes Old C-102 and C-103 Effectivo 1-1-65 |
|-----------------------------|--|---|
| FILE | | Sa. Indicute Type of Lease State Fee XX |
| LAND OFFICE | | |
| OPERATOR | | 5, State Off & Gas Lease No. |
| 1. | Y NOTICES AND REPORTS ON WELLS | 7, Unit Agreement Home |
| | OTHLR. | |
| 2. Name of Operator | | 8. Farm of Lease Hame |
| Gulf Oil Corporation | | H. T. Mattern (NCT-B) |
| 3. Adaress of Operat | | 9. Well No. |
| Box 670, Hobbs, New M | lexico 88240 | 17 |
| 4. Location of Well | | 10. Field and Post, or Willout |
| C 38 | BO FEET FROM THE NOTTH LINE AND 1650 FEET FROM | Drinkard |
| | 31 TOWNSHIP 21-S RANGE 37-E NMPM. | |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | 3510' GL | Lea |
| T6. Check 7 NOTICE OF IN | Appropriate Box To Indicate Nature of Notice, Report or Oth ITENTION TO: SUBSEQUENT | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER Abandoned Blineb | ALTERING CASING DUG AND ADANDONMENT |
| OTHER | and completed in Drinka | rd. |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6810' TD. 6766' PB.

Pulled producing equipment. Squeezed Blinebry perforations 5440' to 5680' with 50 sacks of Class H cement containing 1% CFR-2. WOC 24 hours. Cleaned out and tested Blinebry perforations with 500#, 30 minutes, OK. Drilled 4-3/4" hole to 6810'. Ran 26 joints, 1060' of 4" OD 11.60# J-55 liner. Set bottom of liner at 6809' and top at 5738'. Cemented with 80 sacks of Class H cement containing 1.25% CFR-2. Cement circulated around top of liner. WOC 24 hours. Cleaned out to 6766'. Tested liner with 4,000#, 30 minutes, OK. Perforated Drinkard zone in 4" liner with 4, .39" JHPF at 6488-91', 6533-36', 6566-69', 6612-15', 6631-34', 6666-69', 6703-06' and 6728-31'. Ran treating equipment and treated new perforations with 2,000 gallons of 15% NE acid. Flushed with 28 barrels of brine water. Swabbed and cleaned up. Frac treated with 16,000 gallons of gel brine and 40,000 gallons of gel brine containing 1 to 2# SPG. Flushed with 51 barrels of brine. Pulled treating equipment. Ran 4" packer and 2-3/8" tubing. Set packer at 6445' with 7,000# tension. Swabbed and cleaned up. Ran rods, pump and placed well on production.

| 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | | | |
|--|-----------------|------------|----------|----------------|--|--|
| | F. Berlin | TITLE Area | Engineer | | | |
| | Range of the by | | | BATE SLAT 1976 | | |
| PPROVED BY | Dec 2, Supr. | TITLE | | DATE | | |