

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-3672	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator John H. Hendrix		8. Farm or Lease Name State X
3. Address of Operator 403 Wall Towers West, Midland, Texas 79701		9. Well No. 2
4. Location of Well UNIT LETTER L, 1980 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 20-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Monument-Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3515.6' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Reached TD @ 5300' on 12-24-75 (MST).
- Ran 163 jts. (5331') 4-1/2" H-40, 10.5# csg. set @ 5300'.
- Cmt'd. w/300 sxs. Class C, 50-50 pozmix, 8# salt/sx., 250 sxs. Halliburton lite, 1/4# floccel, 5#gilsonite, 15# salt/sx. Plug down @ 5:45 p.m. (MST) 1-24-75 (MST).
- West Engineering ran temperature survey. Found cement top @ 2830'.
- WOC 18 hrs. Tested to 800# - ok.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Marlin A. [Signature] TITLE Production Clerk DATE 1-27-75

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: