

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON THE OPENED FIELD, OR TO A DIFFERENT RESERVOIR, OR FOR APPLICATION FOR PERMIT - (FORM C-101, FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☒
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		5. State Oil & Gas Lease No.
2. Name of Operator Sun Oil Company		6. Farm or Lease Name Della B. Boren
3. Address of Operator P. O. Box 1861 - Midland, TX 79702		9. Well No. 3
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 20 TOWNSHIP 22S RANGE 36E NW/4.		10. Field and Pool, or Wildcat Eunice Seven Rivers Queen South
15. Elevation (Show whether DF, RT, GR, etc.) 3561.6 GR, 3570.6 RDB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	Completing ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-24 TD 7" csg. seat 4000 ISF 3974 MIRU Go Int. Run GR CCL 3991-3000 Perf 3920-30, 3905-11, 3887-97, 3873-77 1 JSPF, 34 holes. Run 2-3/8 tbg. w/Rdg. Pkr.

8-25 SPTD 120 gals. 51% NEHC across perfs. Set Pkr 3791 Trppd 500 on csg. Western acidize 2000 gals. 15% NEHCL w/5 RCNBS after ea. 200 gals. BDP 2000, MP 2900, AP 2100. Swbd 7 hrs.- Rec. 42 BLAW, Trace - oil.

8-26 SWAB 7-1/2 hrs. Rec. 8 BLAW, TR.-oil. Re-Set Pkr 3787 Western frac perfs. w/24,000 GG 2% KCL 30,000# 20/40 sd. in 3 Eq. Stgs. w/300# 50/50 BAF & GRS.

8-27 Swab 4 hrs. Rec. 40 BLAW & Tr oil. Rlstd. Pkr. tgd fill.

8-28 Put on pump. Run pump, Rods. TS 3950 SN 3925 Set pumping unit.

8-29 Set unit - repair engine.

30-31 " "

9-1 Pump No oil, 34 BLW.

9-2 Pump No oil, 161 BLW, No gas.

9-3,4,5,6 MIRU, pull rods, Swab, Drpd SV, Test tbg. re-run pump & rods.

9-6 Thru 14 Testing - Aug. Test No oil, 136 BW, no gas.

9-14 TA pending additional work.

9-16 MIRU pull rods, install BOP, Pull tbg.

9-17,18, 19 Go set CI Ret at 3860, Howco EIR 4 BPM 1400 sqzd perfs 3873-3930 w/150 sx c Neat

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Carol Muntel* TITLE OFFICE ASSISTANT DATE 9-19-77

APPROVED BY Jerry Sexton TITLE Dist 1, Supv. DATE SEP 21 1977

CONDITIONS OF APPROVAL, IF ANY

RECEIVED

SEP 21 1977

OIL CONSERVATION COMM.
HOBBS, N. M.