Form 9-331 (May 1963) DEPAR	Un. (ED STATES TMENT OF THE INTERI	SUBMIT IN TRIL CATE* (Other instructions on reverse side)	Form approved. Budget Bureau No. 42-R14 5. LEASE DESIGNATION AND SERIAL NO
GEOLOGICAL SURVEY			<u>LC - 046295</u>
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAM
			ing a second of the second
1.		opositio, y	7. UNIT AGREEMENT NAME
OIL X GAS OTHER			T. CALL AGREEMENT NAME
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Marathon Oil Company 3. ADDRESS OF OPERATOR			C. J. Saunders
P.O. Box 2409 Hobbs, NM 88240 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit C, 430' FNL & 2307' FWL			9. WELL NO.
			3 5 5 5 7 7
			10. FIELD AND POOL, OR WILDCAT
			Drinkard 11. SEC., T., B., M., OR BLE, AND
			SURVEY OR AREA
4. PERMIT NO.			Sec. 1, T-22S, R-36E
	15. ELEVATIONS (Show whether DF,		12. COUNTY OR PARISH 18. STAFE
6.	3514.4' GR 35		Lea NM
". Check A	Appropriate Box To Indicate No	ature of Notice, Report, or O	ther Data
NOTICE OF INTE	ENTION TO:		ENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	n 1944 – Primir I – 1
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT+
REPAIR WELL (Other)	CHANGE PLANS	(Other) 9 5/8" casin	o test
	PERATIONS (Clearly state all parti-	Completion or Recomple	f multiple completion on Well tion Report and Log form.
7. DESCRIBE PROPOSED OR COMPLETED OF proposed work. If well is direct nent to this work.) * 1. Spudded well Dece	ember 29. 1978 Drill	ed 12 1//!! bolo #= 120	
3. Cemented 9 5/8" c	', 32#, H-40, ST & C ca asing with 700 sacks o	asing set at 1391' KB class C cement contai	하다 그는 그는 그 말을 뛰어난다.
OHIOTIGE. OIICUL	ared 100 Sacks to bit.		
Manifold, and Kill Lines.			[- [[[[[[[[[[[[[[[[[[
5. Pressure tested Blind Rams, Pipe Rams, Choke Manifold, Kelly, and Velly			
Cock to 3000 psi psi for 15 min.	TOT ID min. Held okay	. Pressure tested H	ydrill to 1500
6. Pressure tested 9	5/8" casing to 1500 r	esi for 30 min Uoli	민습문 이 중 승취상되는 그는
7. Drilled out 9 5/8	" casing shoe and comm	nenced drilling 8 3/4	okay.
		3,4	140 46. # 12.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.
			(1941년 - 일 경투증명 -
		7	RECEIVED
	•	14 4 1	AN 1 0 1979
			(회통화) 한 화 (VI) 위한
			J.S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO
I hereby certify that the foregoing is	true and connect		ិសាធិស្តី មិន ទាំងធ្វីដូ
SIGNED William R. M.		duction Engineer or of	10 DATE 1-9-79
(This space for Federal or State offic	e use)	WEEDLED FOR UTON	4
APPROVED BYCONDITIONS OF APPROVAL, IF A	TITLE	1002	
DELICITION OF AFFRUYAL, IF A		JANITY	WEY SEE
	*See Instructions of	J. S. GEOLOGICAL SU HOBBS, NEW MEX	co.