

## SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☒ gas well ☐ other ☐

3. ADDRESS OF OPERATOR  
P. O. Box 460, Hobbs, N.M. 88240

below.)  
AT SURFACE: 1650' FSL, 890' FEL  
AT TOP PROD. INTERVAL: —  
AT TOTAL DEPTH: —

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL  
PULL OR ALTER CASING  
MULTIPLE COMPLETE  
CHANGE ZONES  
ABANDON\*  
(other) *Snuff, ran su*

SUBSEQUENT REPORT OF:

--	--	--	--	--	--	--	--

(other) spud, ran surface csq

## 5. LEASE

LC-031695(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

NMFU

8. FARM OR LEASE NAME

Warren Unit

9. WELL NO.

86

10. FIELD OF WILDCAT NAME

Warren McKee

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

Sec. 29, T-20S, R-38E

12. COUNTY OR PARISH | 13. STATE

Leaf

N/M

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MIRU 1/4/82. Ran 13<sup>3</sup>/<sub>8</sub>", 54.5<sup>#</sup> csg set at 1448'. Cemented w/ 1032sx Class C, tail w/ 200sx Class C cmt. Circulated 300sx to surface.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE \_\_\_\_\_

~~FEB 1 1982~~

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL \_\_\_\_\_  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

TITLE

DATE \_\_\_\_\_