STATE OF NEW MEXICO	
UNERIGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501	Form C-103 Revised 19-1-78
PILE U.S.O.S.	a, Indicato Type of Leaso State State Foo X S, State Otl & Gus Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO CRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 100 NOT USE THIS FORM FOR PROPOSALS TO CRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	7. Unit Agreement Name
Division of Atlantic Richfield Company	8. Farm of Lease Name <u>H. S. Record "Oil" WN</u> 9. Well No. 5
. Location of Well N 860 FEET FROM THE LINE AND FEET FROM THE	10. Field and Pool, or Wildcat Eunice 7R Qn So.
13. Elevention Ishow whether or any only and	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other NOTICE OF INTENTION TO: SUBSEQUENT	Lea ())))))))))))))))))))))))))))))))))))
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. X TEMPORARILY ABANDON PULL OR ALTER CABING CHANGE PLANS CHANGE PLANS OTHER	ALTERING CASING
OTHER	stimated date of starting any proposed

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimates are of starting any proposed work) SEE RULE 1903.

Spudded 12¹/₄" hole @ 10:00 PM 1/31/81. Finisheddrlg to 1011' @ 4 AM 2/2/81. RIH w/8-5/8" OD 24# K-55 csg set @ 1100', FC set @ 1028'. Cmtd 8-5/8" OD csg w/550 sx Cl C cmt cont'g 4% gel followed by 250 sx Cl C cmt w/2% CaCl₂. Circ 135 sx cmt to pit. PD @ 1:45 PM 2/2/81. WOC 11-3/4 hrs. The following cement compressive strength criterion is furnished for cmtg in accordance w/ Oil Conservation Division Rules & Regulations:

- The volume of cement slurry used was 919 cu ft of Cl C cmt cont'g 4% gel followed by 330 cut ft of Cl C cmt w/2% CaCl₂. Circ 225 cu ft of cmt to pit.
- 2. Approximate temperature of cement slurry when mixed was 68° F.
- 3. Estimated minimum formation temperature in zone of interest was 72° F.
- 4. Estimate of cement strength at time of casing test was 1100 PSIG.
- 5. Actual time cement in place prior to starting test was 11-3/4 hrs. Pressure tested csg to 1000# for 30 mins, OK. Drlg 7-7/8" hole @ 1:30 AM, 2/03/81.

if. I hereby certify that the information above is true and con	mplete to the best of my knowledge and belief.	
NICHED Journ Schmidt	Dist. Drlg. Supt.	DATE
APPROVED BY		ATE ST 5 1 2 1981
CONDITIONS OF APPROVAL, IF ANY:	TITLE	