




TEXACO INC.  
GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

C. H. L. S. R. A. #12  
ON 11:00 AM  
2-12-90

OFF 9:15 AM  
2-13-90  
Chart #1  
BR 2221

UPPER  
Shunt in #536  
Drunkland  
Lower  
Shunt in #470  
No. 1