

UNITED STATES N. M. OIL CONS. COMMISSION
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO

LC-063458

ALLOTTEE OR COAL NAME

MINISTRY INTERESTS AND REPORTS ON WELLS

1. This report is for a well to drill or to deepen or plug back to a different depth (specify depth in feet) (b) (specify depth in feet)

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR

CHAPMAN, INC.

3. ADDRESS OF OPERATOR

1000 E. 10th St. Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below)

AT SURFACE: 1000 E. 10th St.

AT TOP 1500' DEPTH: 1000 E. 10th St.

AT DEPTH 1500': 1000 E. 10th St.

5. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, BEFORE, OR UNDER DATA

7. UNIT AGREEMENT NAME

1000

8. TOWN OR RANGE NAME

Chapman Unit

9. WELL NO.

10. FIELD OR WELLBORE NAME

1000 E. 10th St.

11. SEC., T., R., S., OR DEK. (SEE INSTRUCTIONS)

Sec. 35, T. 20S, R. 43E

12. COUNTY OR PARISH

Lea

13. STATE

14. ALT. NO.

15. ELEVATIONS (SHOW DE, KDB, AND TD)

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACURE TEST

SHOOT OR PERMITS

REPAIR WELL

PULL OR RIGGING CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(Check one box)

SUBSEQUENT REPORT OF:

RECEIVED
DEC 16 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give surface coordinates and measured and true vertical depths for all markers and zones pertinent to this work)*

Reached TD of 7750' on 12/11/81. Ran 7", 26" KSS, LIC csg set at 7750'; FC at 7708'; DV at 7576'. 1st stage cement: 5455x Class C lite, tail w/ 200x Class C. 2nd stage cement: 2237x Class C, tail w/ 200x Class C. Circulated 425x cat. to surface

Set surface Safety Valve Manu. and Type

Set @

ft.

18. I hereby certify that the foregoing is true and correct

SIGNED: *Roger A. Chapman*

TITLE: *Manager, Oil & Gas*

DATE: *December 15, 1981*

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY: *ROGER A. CHAPMAN*
COMPLETION OF APPROVAL, IF ANY:

DEC 17 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See instructions on reverse side