

## WELL INCLINATION SURVEY

I, Randy A. McClay, certify the following is the correct hole inclination survey for the well as described below:

Tamarack Petroleum Co., Inc., \_\_\_\_\_  
(Company or Operator) (Lease)

Danglade Well No. 1

in NW 1/4 of SW/4, of Sec 9, T 20-S,

R 38-E, NMPM. W. Nadine Blinebry Pool, \_\_\_\_\_

Lea County. Well is 1980 feet from the \_\_\_\_\_

south line and 660 feet from the west line of

Section 9.

Depth(Feet)	Inclination(Degree)	Depth(Feet)	Inclination(Degree)
-------------	---------------------	-------------	---------------------

357	1/2		
698	1/2		
1255	3/4		
2082	3/4		
3272	1 3/4		
3817	1 3/4		
4314	1 1/4		
4903	2		
5788	1 1/2		
6763	1 3/4		
7100	1		

Tamarack Petroleum Company Inc.  
(Company or Operator)

By Randy A. McClay

Title District Engineer

Subscribed and sworn to before me  
this 12th day of October,  
19 81.

Vanessa K. Miller  
Vanessa K. Miller  
Notary public in and for Midland  
County, Texas.