

Form 9-331
Dec. 1973

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
ROSWELL, NEW MEXICO 88240

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR
Amoco Production Company

3. ADDRESS OF OPERATOR
P. O. Box 68, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980 FNL x 2090 FWL Sec. 19
AT TOP PROD. INTERVAL: (Unit F, SE/4, NW/4)
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☒
☐
☐
☐
☐
☐

5. LEASE
NM 17441

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
El Alto Grande

9. WELL NO.
1-Y

10. FIELD OR WILDCAT NAME
Wildcat Devonian

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
19-22-34


12. COUNTY OR PARISH
Lea

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3461.8 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)



OIL & GAS
U.S. GEOLOGICAL SURVEY

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in service unit 4-23-82. Ran 2-7/8 tubing and packer. Tested tubing to 8000 psi and tested O.K. Packer set at 13,498 ft. Installed tree, dropped bar and perforated interval 13631-73'. Swabbed and no show of gas. Acidized with 3,500 gal of 7-1/2% MS x 136000 SCF N2 with additives. Swabbed 9 hrs. and recovered 12 bbls of water. Last hr. recovered 1 bbl of water and 6 ft. flare. Currently shut in until additional work is done.

0+4-USGS,R 1-HOU 1-W. Stafford 1-MDR
Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Mark Randolph TITLE Admin. Analyst DATE 6-4-82

ACCEPTED FOR RECORD
(ORIG. SGD.) DAVID L. GLASS
(This space for Federal or State office use)

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

OCT 20 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED
OCT 22 1982
C.C.D.
HOBBS OFFICE