

N. M. OIL CONS. COMMISSION

Form 9-331
(May 1963)

P. O. BOX 1930

UNITED STATES

SUBMIT IN TRIPL
(Other instructions
verse side)E*
re-Form approved.
Budget Bureau No. 42-R1424.

HOBBS, NEW MEXICO DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. NM - 23768
2. NAME OF OPERATOR BTA OIL PRODUCERS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 104 South Pecos Midland, Texas	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FWL	8. FARM OR LEASE NAME Maddox Federal B. 8016 JV- 9. WELL NO. Fed. 1
14. PERMIT No. date 9/3/82	10. FIELD AND POOL, OR WILDCAT Antelope Ridge (Morrow)
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3405' GR	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35, Twp. 22-S, Rge. 34-E
	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/12/83 Cmtd 7-3/4" Liner From 11,172' to 12,899' w/ 350 sx. WOC.

1/13/83 Tested Liner to 2000 psi for 30 min. OK. Drlg 6 1/2" hole.

2/3/83 Cmtd 5" Liner from 12,584' to 13,649' w/225 sx. WOC.

2/4/83 Tested Liner to 2000 psi for 30 min. OK.

2/7/83 Released Rig @ 2:00 P.M. Prep to complete.

18. I hereby certify that the foregoing is true and correct

SIGNED

BOB K. NEWLAND

(This space for Federal or State office use)

TITLE Regulatory Administrator

DATE 5/9/83

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

AUG 24 1983

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO

N. M. OIL CONS. COMMISSION
UNITED STATES P. O. BOX 1880
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE
REVERSE SIDE

240E*

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-23768

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Maddox Federal-B-, 8016JV.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Antelope Ridge (Morrow)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 35, Twp. 22-S,
Rge. 34-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

BTA OIL PRODUCERS

3. ADDRESS OF OPERATOR

104 South Pecos Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3405' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud & Casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

9/28/82 Spudded @ 11:00 AM - Drlg 12" hole in sand.

10/13/82 Reamed 12" hole to 26". Drlg 26" hole in red beds.

10/22/82 Cmtd 20" csg @ 1661' w/2600 sx. Circ cmt. WOC.

10/23/82 Tested csg & BOP's to 500 psi for 30 min. OK. Drlg 17½" hole.

11/8/82 Cmtd 13-3/8" csg @ 5225' w/3600 sx. TOC @ 97'. WOC.

11/9/82 Tested csg & BOP's to 1500 psi for 30 min. OK. Drlg 12¼" hole.

12/20/82 Cmtd 9-5/8" csg @ 11,720' w/ 2400 sx. Circ thru DV Tool @ 5521'. WOC. No show of cmt

12/21/82 Cmtd second stage w/1300 sx PD: 12:30 PM. Circ cmt. WOC.

12/22/82 Tested csg & BOPS to 2500 psi for 30 min. OK. Drlg 8½" hole in shale & lime.

12/23/82 Drlg Ahead...

18. I hereby certify that the foregoing is true and correct

SIGNED

BOB K. NEWLAND

TITLE Regulatory Administrator

DATE 12/24/82

(This space for Federal ACCEPTED FOR RECORD

APPROVED BY
CONDITIONS OF

(ORIG. SGD.) DAVID R. GLASS

TITLE

DATE

APPROVAL, IF ANY:

JAN 13 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

See Instructions on Reverse Side

MINERALS

ROSWELL, NEW MEXICO