N.M. Oil Cr. \ Division 1625 N. French Dr.

TYPE OF ACTION

Run Casing Integrity Test

Form 3 160-5 (June 19 0)

UNITED STATES Hobbs, NM 88240 DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 3 1 ,1993

Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

LC 031670B 6. If Indian, Allottee or Tribe Name

Change of Plans

New Construction

Water Shut-Off

Dispose Water

Non-Routine Fracturing

Conversion to Injection

SUBMIT IN TRIPLICA 1	7. If Unit or CA, Agreement Designation
1. Type of Well	
○il	8. Well Name and No.
2. Name of Operator	SEMU #121
Conoco Inc	9. API Well No.
3. Address and Telephone No. 10 DESTA DR. STE. 100W, MIDLAND, TX 79705-4500 (915) 686-5580	30-025-29089
	U (915) 080-5580 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T. R. M. or Survey Description)	Eumont Yates 7 Ryrs/Queen
660' FSL & 2310' FWL, Sec. 18, T20	DS, R38E, N
	Lea, NM
CHECK APPROPRIATE BOX(s) TO INDICAT	E NATURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION

Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Abandonment

Recompletion

Plugging Back

Casing Repair

Altering Casing

In December, Conoco attempted a recompletion in the Eumont Yates Seven Rivers/Queen pool and it was unsuccessful. During this recompletion attempt, a CIBP was set @ 6600', tested to 7000# and it held. A production packer was set @ 2890' and tested to 2500# and it held. The packer was then set @ 2912' and the backside tested to 1000# and again, it held. The well has since been shut in for evaluation. Conoco would like to run a CIT in preparation to request Temporary Abandon status, per the following procedure:

- 1. RU pulling unit. Load the tubing. Install and test BOP stack.
- 2. Release the packer and TOOH with 3 1/2" tubing.
- 3. RIH w/CIBP for 7" OD casing and set @ 2960'.
- 4. TIH with 3 1/2" tubing, tag the CIBP, load casing with packer fluid and test casing to 1000#.
- 5. TOOH laying down 3 1/2" tubing.

Notice of Intent

Subsequent Report

Final Abandonment Notice

6. ND BOP stack. Install adapter flange with a valve on the tubing head. RDMO

Conoco is preparing this well for Temporary Abandonment status in order to evaluate uphole Yates potential. This evaluation should be completed in 6 to 8 months.

ORIG. SGD.) ALEXIS C. SWOBODA Title PETROLEUM ENGINEER Date FED C	
Approved by Approv	03/00
Conditions of approval if any:	9 2000

BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE ROOM, FIELD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.