

- 10-03-91 - Max - 3100 psig. Avg - 20 bpm - 2920 psig. ISIP - 1200 psig. P5 min - 1150 psig. P10 min - 1150 psig. P15 min - 1130 psig. RD Western. SWIFN.
- 10-04-91 - No report. Shut down for frac to cure.
- 10-05-91 - SITP = 0 psig. WIH w/swab. FL - 2500' FS. Made 12 runs in 4 hrs & recov'd 48 BW. EFL - 3500'. Released pkr. RIH & tagged @ 3690' (perfs 3636-3727'). POOH w/tbg & pkr. RIH w/hydrostatic bailer on 2 7/8" J-55 tbg. Bailed out frac sand to PBTD - 3742'. POOH w/tbg & bailer. RIH w/ 2 7/8" prod string. SWIFN.
- 10-06-91 - ND BOP. NU tree. RIH w/pump & rods. Hung well on. Load & test. Well pumping OK. RD PU. Left well pumping to frac tank.
- 10-07-91 - No test. Well not pumping.
- 10-08-91 - RU PU. Changed out rod pump. Load & test pump. OK. RD PU. Left well pumping to frac tank. Found frac sand in pump.
- 10-09-91 - Well pumped 1 BO & 139 BW & 20 MCFPD in 24 hrs. Shut well in.

FINAL REPORT.