

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31588
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1651-9
7. Lease Name or Unit Agreement Name NORTH MONUMENT GRAYBURG SAN ANDRES UNIT BLK 6	
8. Well No.	18
9. Pool name or Wildcat	EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3678 GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator AMERADA HESS CORP.
3. Address of Operator ATTN: DRLG SVS. 1201 LOUISIANA STE. 700 HOUSTON, TX. 77002	4. Well Location Unit Letter <u>B</u> : <u>1310</u> Feet From The <u>NORTH</u> Line and <u>2544</u> Feet From The <u>EAST</u> Line Section <u>20</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3678 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
FULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SPUDDED 17½" HOLE @ 8 P.M. 09-28-92. SET 11 JTS (477') 10 3/4" 48# H-40 8R5 ERW IN 17½" HOLE. BJ SERVICES CEMENTED WITH 500 SX CLASS "C" + 2% A-7, SW= 14.8, SY= 1.32. PLUG ON BOTTOM AT 10:30 09-29-92. FLOAT EQUIPMENT HELD. CIRCULATED 108 SX TO PIT. WOC 18½ HOURS. TESTED CASING TO 1000 PSI FOR 30 MINUTES.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Betsy Williams TITLE Petroleum Engineer DATE 10-1-92
TYPE OR PRINT NAME Betsy Williams TELEPHONE NO. (713) 752-5437

(This space for State Use)

Orig. Signed by
Paul Kanta
Geologist

APPROVED BY _____ TITLE _____ DATE OCT 06 1992
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
OCT 05 1992
OCD HOBBS OFFICE