

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-31600

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

VB-134

7. Lease Name or Unit Agreement Name

Kiwi AKX State

8. Well No.

4

9. Pool name or Wildcat

E. Livingston Ridge Delaware

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter 0 : 330 Feet From The South Line and 1650 Feet From The East Line

Section 16

Township 22S

Range 32E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3705' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Set production casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8760'. Reached TD 6-25-92. Ran 207 joints 5-1/2" 15.5# and 17# J-55 casing set 8760'. Float shoe set 8760', float collar set 8719'. DV tool set 7528'. Cmt'd in two stages. Stage I - 200 sx "H" w/8#/sx CSE, .6% CF-14, 5#/sx Gilsonite, 35% ThriftyLite (yield 1.75, wt 13.6). PD 12:47 AM 6-27-92. Bumped plug to 1000 psi for 1 minute, OK. Circulated 50 sacks to surface. Circulated thru DV tool 3 hrs. Stage II - 738 sx "H" w/8#/sx CSE, .5% CF-14, 5#/sx Gilsonite, 35% ThriftyLite (yield 1.82, wt 13.3). PD 4:53 AM 6-27-92. Bumped plug to 2500 psi for 1 minutes, OK. WOC 24 hrs. Drilled out DV tool at 7528'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Supervisor

DATE 7-7-92

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 09 '92