

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31645
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB 134

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Kiwi AKX State
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 6
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat East Livingston Ridge Delaware
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>22S</u> Range <u>32E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3696' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole 10:00 AM 7-24-92. Set 40' of 20" conductor. Notified Joan, NMOCD, Hobbs, NM at spud. Resumed drilling 17 1/2" hole 1:15 PM 8-3-92. Ran 20 joints 13-3/8" 54.5# casing set 852'. Guide shoe set 852'. Insert float set 809'. Cemented w/550 sx PSL "C" w/2% CaCl2 (yield 1.98, wt 12.4). Tail in w/250 sx Class "C" w/2% CaCl2 (yield 1.32, 2 5 14.6). PD 3:30 PM 8-4-92. Bumped plug to 500 psi, float held OK. WOC. Drilled out 9:30 AM 8-5-92. WOC 18 hours. NU and tested to 500 psi for 30 minutes, OK. Reduced hole to 11".
Note: Notified NMOCD, Hobbs, NM, to witness - did not witness.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 8-11-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

AUG 13 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 18 1992

RED MAPS OFFICE