

BURLINGTON RESOURCES
RED TANK, WELL #3
LEA COUNTY, NEW MEXICO

Page 3

MEASURED Depth Feet	B O R E - H O L E		TRUE Vertical Depth Feet	R E C T A N G U L A R C O O R D I N A T E S		VERTICAL SECTION Feet	C L O S U R E S		DLS Deg/100'
	Incl. D M	Direction D M		North/South Feet	East/West Feet		Distance Feet	Direction D M	
8000.00	0 45	S 78 0 W	7996.19	54.34 N	85.21 E	54.34	101.07	N57 28E	.27
8200.00	1 0	S 63 0 W	8196.16	53.33 N	82.34 E	53.33	98.10	N57 4E	.17
8400.00	0 45	S 53 0 W	8396.14	51.71 N	79.75 E	51.71	95.05	N57 2E	.15
8600.00	1 0	S 55 0 W	8596.12	49.91 N	77.28 E	49.91	91.99	N57 8E	.13
8711.00	1 15	S 54 0 W	8707.09	48.65 N	75.50 E	48.65	89.82	N57 12E	.23

Final Station Closure Distance: 89.82 Feet; Direction: N 57 12 E