

**DUPLICATE**

# **OIL CONSERVATION COMMISSION**

Santa Fe, New Mexico

## **MISCELLANEOUS REPORTS ON WELLS**

**RECEIVED**  
JUL 10 1947  
**HOBB'S OFFICE**

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<b>X</b>		

July 7, 1947

Date

Monument, New Mexico

Place

OIL CONSERVATION COMMISSION,  
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the  
Amerada Petroleum Corporation State SLA Well No. 1 in the

Company or Operator Lease  
SE $\frac{1}{4}$  SE $\frac{1}{4}$  of Sec. 24, T. 21S, R. 33E, N. M. P. M.,  
Lea Field, Lea County.

The dates of this work were as follows: July 6, 1947

Notice of intention to do the work was ~~(cross out)~~ submitted on Form C-102 on July 5 19 47  
and approval of the proposed plan was ~~(cross out)~~ obtained. (Cross out incorrect words.)

### **DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED**

6370' Total Depth Line. Went in hole with drill pipe and plugged back from 6370' to 6282' with 20 sacks Atlas Common cement and flushed with 43½ bbls. mud @ 12:20AM. Plugged from 4470' to 4382' with 20 sacks Atlas Common cement and flushed with 32 bbls. mud @ 2:15AM. Plugged back from 1916' to 1828' with 20 sacks Atlas Common Cement and flushed with 13.6 bbls. mud @ 4:15AM. Took off connections, went in hole and shot off casing @ 552' with one shot. Recovered 13 jts., 533' 10" of 7-5/8" OD, 26.40#, J-55, R-3, 8-RT, SS Casing. Ran top plug with 20 sacks Atlas Common Cement @ 3:00PM, 4" Pipe Marker 5' High placed in center of cement cap.

Witnessed by Don Topper Amerada Pet. Corp. Asst. Dist. Supt.  
Name Company Title

Subscribed and sworn before me this

I hereby swear or affirm that the information given above is true and correct.

8th. day of July, 19 47

Name Don Topper

Position Asst. Dist. Supt.

Wille Hailer Taylor  
Notary Public

Representing Amerada Pet. Corp.  
Company or Operator

My commission expires My Commission Expires May 9, 1948

Address Drawer D, Monument, New Mexico

Remarks:

**APPROVED**

Date JUL 10 1947

W. J. Yarbrough  
Name  
**Oil & Gas Inspector**