

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

54. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
55. State Oil & Gas Lease No.	B-10792

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Temp. abandon	7. Unit Agreement Name
2. Name of Operator WILSON OIL COMPANY	8. Farm or Lease Name State (B10792) Btry 2
3. Address of Operator P. C. Box 457, Artesia, New Mexico 88210	9. Well No. 24
4. Location of Well UNIT LETTER L 1650 FEET FROM THE South LINE AND 330 FEET FROM West 24 21 34 THE LINE, SECTION TOWNSHIP RANGE N.M.P.M.	10. Field and Pool, or Wildcat Wilson (Y-7R)
15. Elevation (Show whether DF, RT, GR, etc.) 3645' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On May 4, 1971, well was plugged and abandoned according to approved Notice of Intention dated March 12, 1971.

50 sx cement plug 3547' to 3792'
Plug did not shut off bottom of hole
A second 50 sx cement plug was set 3547'-3792'
Unable to pull 7" casing
25 sx cement plug set in top 7" casing with regulation marker
8-1/2# native mud between cement plugs.

Location ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>N. K. Lant</i>	TITLE Vice President	DATE Oct. 12, 1971
APPROVED <i>Nathan E. Pegg</i>	TITLE	DATE DE 1971
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

001 131971

OIL CONSERVATION CLUB
HOBBS, N. M.