


NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS



Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other) Sand Frac	X

January 25, 1954
(Date)

Artesia, New Mexico
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Charm Oil Company

Gulf State
(Lease)

(Company or Operator)

J. P. Gibbens

(Contractor)

Well No. **1** in the **se** $\frac{1}{4}$ **sw** $\frac{1}{4}$ of Sec. **1**

T. **218**, R. **35E**, NMPM, **Undesignated** Pool, **Lea** County.

January 11, 1954

The Dates of this work were as follows:

Notice of intention to do the work (was) ~~(was not)~~ submitted on Form C-102 on **January 8**, 19**54**,
(Cross out incorrect words)

and approval of the proposed plan (was) ~~(was not)~~ obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Attempted to sand frac through perforations from 3756 to 3804'. Could not isolate zone. Completed well as gas well w/plugged back depth of 3804'. 2" EUE tubing at 3450'.

Witnessed by _____ (Name) _____ (Company) _____ (Title)

Approved: _____ OIL CONSERVATION COMMISSION

S. G. Stanley
(Name)

(Title)

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name **Viles P. Allison**

Position **Agent**

Representing **Charm Oil Company**

Carper Bldg., Artesia, N.M.

Address _____