


NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Resler and Sheldon		Address 302 Carper Building, Artesia, New Mexico				
Lease Amerada State	Well No. 1	Unit Letter C	Section 3	Township 21S	Range 35E	
Date Work Performed April 2, 1959	Pool Ramont		County Lea			
THIS IS A REPORT OF: (Check appropriate block)						
<input type="checkbox"/> Beginning Drilling Operations <input type="checkbox"/> Casing Test and Cement Job <input type="checkbox"/> Other (Explain):						
<input type="checkbox"/> Plugging <input type="checkbox"/> Remedial Work						
Detailed account of work done, nature and quantity of materials used, and results obtained. Spudded April 1, 1959. Drilled 11" hole to 257'. Ran 8 5/8" casing to 257'. Cemented with 200 sacks which circulated. Let stand 16 hours. Pressured to 800 p.s.i. and held o.k. for 30 hours. Drilled plug and again pressured to 800 p.s.i. Held o.k. so resumed drilling.						
Witnessed by		Position		Company		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	T D		P B T D	Producing Interval	Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter	Oil String Depth	
Perforated Interval(s)						
Open Hole Interval			Producing Formation(s)			
RESULTS OF WORKOVER						
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.		
Approved by 				Name Vilas O. Sheldon		
Title				Position Partner		
Date				Company Resler and Sheldon		

1