						•	
• • • • •	OF NEW MEXICO						
	AINERALS DEPARTMENT				• .		
· _	IBUTION		ATION DIVISIO	N		Farm 6 144	
	BANTA FE SANTA FE, NEW MEXICO 87501				Form C-103 Revised 10-1- 7		
FILE			W MEXICO 8/301		Sa. Indicate Type of	1	
U.S.O.S.					Stote X	F	
OPERATO					5. State Oil 6 Ges L		
L							
	SUNDRY NOT	ICES AND REPORTS O	N WELLS			<u>IIIIIII</u>	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)							
). ●!⊾ []]	6A8 0THE	_			7. Unit Agreement N	ome	
2. Name of Opera	tor				8. Form or Lease Ha	De	
ARCO OIL & GAS COMPANY Division of Atlantic Richfield Company							
3. Address of Operator					Endura DE State		
P.O. Box 1710 Hobbs, New Mexico 88240					4		
14, Location of Well					10. Field and Pool, or Wildon		
WHIT LETTER 1980 FEET FROM THE South LINE AND 660 FEET FROM					Eumont Yates 7R Qn		
-	10		~ =			THIIII	
. THE Las	StLINE, SECTION 12	томнанар21	RANGE35				
11. Elevation (Show whether DF, RT, GR, etc.)					12, County	<i>\\\\\\\\</i>	
					Lea		
if. Check Appropriate Box To Indicate Nature of Notice, Report or Ot							
-	NOTICE OF INTENTI			-	REPORT OF:		
PERFORM REMEDIA		PLUG AND ABANDON	REMEDIAL WORK		ALTERING (
TEMPORARILY ABA	***		COMMENCE DRILLING OPHI	• 🔲 -	PLUE AND A	BANDONMENT	
PULL OR ALTER CA	SIN6	CHANGE PLANS	CABING TEST AND CEMENT			~	
			OTHERComming		0i1 & Gas	X	
•••••			Rule 81		•		
17. Describe Prop work) SEE Ru	posed or Completed Operations (Clearly state all pertinent de	tails, and give pertinent da	tes, including e	estimated date of start	ing any proposed	
	•						
4-20-88	MIRU, POH w/rods &	pump. ND wellhes	ad, kill well w/3	0 bbls of	2% KCL water	. NU BOP,	
	Unseat packer, POH	w/tubing. Pick-u	p Mill, 6 drill c	ollars &	2 jts of 2 - 7/8	3" workstr:	
4-21-88	SION BIL u/rest of work	otring Milled	m Nodal Daasham	N-J- 10			
4-21-00	RIH w/rest of work	string. Milled (on model D packer	Made 18	. SION		
4-22-88	POH w/work string	Exchange mill &]	RIH w/mill withou	t packer	picker. Milled	lout Model	
	D & work to 3863	could not get any	further. POH w/	work stri	ng & recovered	l packer.	
	RIH w/4-3/4" bit,	could not clean or	ıt.			-	
(22.00	POH & SION						
4-23-88	RIH w/taper top, f WIH w/ wash pipe	isned part of Otis	s cneck vaive. W	IH W/tape	r tap, broke t	ap into.	
4-24-88	WIH w/wash pipe WIH w/mill & clean	out to PBD. POH	aving workstring	down s	hut down becau	ise of	
	high wind.			COMILE D.			
4-25-88	RIH w/CA Rig down	L					
	Test 5-6,88 16	BO, 33 BW. 10	5 MCFG @ 6-54"	SPM CP	20		
18.] hereby certify	y that the information above is to	rue and complete to the best	of my knowledge and belief.	•			
-	0/ 1						
114HED	any ash	TITLE	Services Supv.	•	DATE 5-9	88	
	IAL SIGNED BY HERY SEX	TON					
V CRIGIN	PIDE VICE I SUI CAVISTOR	, y we'' 1		_	ΜΔΥ	1 8 1998	
APPR 8463 87		TITLE		•	DATE	T C IJUU	
CONDITIONS OF	APPROVAL, IF ANY:			- 7 * C	1 2	C*	

Received May 9 1988 Norse Carice