NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission District Office within fen days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	cate nature of repo	rt by checking belov	7.	
EPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON R	EPAIRING WELL	
EPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING		ISE
EPORT ON RESULT OF TEST OF CASI SHUT-OFF	NG	REPORT ON D	EEPENING WELL	
EPORT ON RESULT OF PLUGGING OF	WELL			
	May 23, 19	55 Date	Dallas, Te	Xas
		Date)	Place
ollowing is a report on the work done and t	he results obtained u	inder the heading not	ed above at the	***************************************
Bright & Schiff	Superior-S	tate	Well No1	in tl
Bright & Schiff Company or Operator NE 1/4 of SW 1/4 of Se	25	., T. Lease 21_S	, _R 35–E	, N. M. P. M
Undesignated Pool				
ne dates of this work were as follows:				
nd approval of the proposed plan was (was : DETAILED ACCO rforated 38842 to 3886 with 9 bbls. oil - 3400 psi. Treat ac. mixed 1# sand per gallon.	not) obtained. (Cross DUNT OF WORK D) holes. Set ted perforation Injection p	out incorrect words. ONE AND RESULT packer at 3870 ns with 20,000 ressure 5500 p	S OBTAINED and broke forma gallons Western si, rate 8 bbls.	tion with Co. crude
nd approval of the proposed plan was (was a DETAILED ACCOUNT for a 1884 to 3886 with 9 bbls. oil - 3400 psi. Treat ac. mixed 1# sand per gallon. Terflushed with 15 bbls. oil. bing and well commenced flowing a per gallon, the sand was recovered, conducted PC	not) obtained. (Cross OUNT OF WORK D) holes. Set ; ted perforation . Injection pr Left well stang at a rate (out incorrect words. ONE AND RESULT packer at 3870 ns with 20,000 ressure 5500 p anding at 1500 of 10 bbls. oi	s OBTAINED and broke forma gallons Western si, rate 8 bbls. psi for 8 hours l per hour. Aft	tion with Co. crude per minut Opened er all los
DETAILED ACCORDINATION OF THE PROPERTY OF THE	not) obtained. (Cross OUNT OF WORK D) holes. Set ted perforation . Injection p Left well stang at a rate OTE test - 101	out incorrect words. ONE AND RESULT packer at 3870 ns with 20,000 ressure 5500 p anding at 1500 of 10 bbls. oi bbls oil, 24	and broke forma gallons Western si, rate 8 bbls. psi for 8 hours l per hour. Aft hours, 1/2 choke	tion with Co. crude per minut Opened er all loa
DETAILED ACCO rforated 3884 to 3886 with 9 bbls. oil - 3400 psi. Treat ac. mixed 1# sand per gallon. erflushed with 15 bbls. oil. bing and well commenced flowi 1 was recovered, conducted PC th no water.	not) obtained. (Cross OUNT OF WORK D) holes. Set ; ted perforation . Injection pr Left well stang at a rate (out incorrect words. ONE AND RESULT packer at 3870 ns with 20,000 ressure 5500 p anding at 1500 of 10 bbls. oi bbls oil, 24	s OBTAINED and broke forma gallons Western si, rate 8 bbls. psi for 8 hours l per hour. Aft	tion with Co. crude per minut Opened er all los
DETAILED ACCO rforated 3884 to 3886 with 9 bbls. oil - 3400 psi. Treat ac. mixed 1# sand per gallon. erflushed with 15 bbls. oil. bing and well commenced flowi 1 was recovered, conducted PC th no water.	not) obtained. (Cross OUNT OF WORK D) holes. Set ted perforation Left well sta ing at a rate of OTE test - 101	out incorrect words. ONE AND RESULT packer at 3870 ns with 20,000 ressure 5500 p anding at 1500 of 10 bbls. oi bbls oil, 24 I hereby swear or a is true and correct. Name And Andrew	and broke forma gallons Western si, rate 8 bbls. psi for 8 hours l per hour. Aft hours, 1/2 choke	tion with Co. crude per minut Opened er all loa , 100 psi
DETAILED ACCO rforated 3884 to 3886 with 9 bbls. oil - 3400 psi. Treat ac. mixed 1# sand per gallon. reflushed with 15 bbls. oil. bing and well commenced flowi 1 was recovered, conducted Po th no water. Vitnessed by. Joe C. Gourlay Name	not) obtained. (Cross OUNT OF WORK D) holes. Set just a perforation pure Left well string at a rate of the country test - 101. Bright SION	out incorrect words. ONE AND RESULT packer at 3870 ns with 20,000 ressure 5500 p anding at 1500 of 10 bbls. oi bbls oil, 24 I hereby swear or a is true and correct. Name Produc	and broke forma gallons Western si, rate 8 bbls. psi for 8 hours l per hour. Aft hours, 1/2 choke District Engineering John	tion with Co. crude per minut Opened er all loa , 100 psi
or forated 3884 to 3886 with 9 bbls. oil - 3400 psi. Treat rac. mixed 1# sand per gallon. Verflushed with 15 bbls. oil. abing and well commenced flowing and well commenced flowing the no water. Witnessed by Joe C. Gourlay Name	ount obtained. (Cross ount of Work D) holes. Set perforation in left well standard a rate of the standard bright. Bright Name	out incorrect words. ONE AND RESULT packer at 3870 ns with 20,000 ressure 5500 p anding at 1500 of 10 bbls. oi bbls oil, 24 I hereby swear or a is true and correct. Name Produc	and broke forma gallons Western si, rate 8 bbls. psi for 8 hours l per hour. Aft hours, 1/2 choke	tion with Co. crude per minut Opened er all loa , 100 psi

Dallas, Texas