

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.  
**B-244**

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>	8. Farm or Lease Name <b>H. T. Orcutt (NCT-F)</b>
3. Address of Operator <b>Box 670, Hobbs, New Mexico 88240</b>	9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>H</b> , <b>1650</b> FEET FROM THE <b>North</b> LINE AND <b>330</b> FEET FROM <b>East</b> LINE, SECTION <b>25</b> TOWNSHIP <b>21-S</b> RANGE <b>35-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Eumont</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3612' GL</b>	12. County <b>Lea</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

**Cleaned out, reperforated and acidized**

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**3946' PB.**

Pulled rods, pump and tubing. Cleaned out to 3946' with sand pump. Reperforated 5-1/2" casing with 2, 1/2" JHPF at 3922-28', 3889-3903' and 3875-85'. Treated perforations with 3000 gallons of 15% NE acid. Flushed with 15 barrels of oil. AIR 5.3 bsm. Ran rods and pump and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY

C. D. BORLAND

SIGNED

TITLE **Area Production Manager**

DATE **April 15, 1968**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: