

DUPLICATE

(Form 7)  
(Revised 7-1-52)

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON

RECEIVED  
JUN 23 1953  
OIL CONSERVATION COMMISSION  
SANTA FE, N.M.

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 30 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test or casing shut-off, plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	XX	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

June 15, 1953 (Date) Artesia, N.M. (Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Charm Oil Company  
(Company or Operator)

Atlantic-State  
(Lease)

Gackle Drilling Company  
(Contractor)

Well No. 1 in the NE 1/4 SE 1/4 of Sec. 25

T. 21, R. 35, NMPM, Eunice Pool, Lea County

The Dates of this work were as follows: June 7, 1953

Notice of intention to do the work (was) ~~not~~ submitted on Form C-102 on June 7, 1953  
(Cross out incorrect words)

and approval of the proposed plan (was) (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

15 sacks cement plugs were set at 3600', at 1600' and at 210'.  
Hole was left full of rotary mud between cement plugs. Regulation marker was set in cement. Location leveled.

Witnessed by E. A. Hales (Name) Gackle Drilling Co. (Company) Pusher (Title)

Approved: OIL CONSERVATION COMMISSION  
P. A. Johnson (Name)  
(Title) (Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.  
Name: Eileen P. Sheehan  
Position: Manager  
Representing: Charm Oil Company  
Address: Garper Bldg., Artesia, N.M.