

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY RESLER AND SHELDON 300 Carper Bldg., Artesia, New Mexico
(Address)

LEASE Gulf State WELL NO. 1 UNIT E S 28 T 21S R 35E
DATE WORK PERFORMED _____ POOL San Simon

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

In conformance with telephone conference the well was plugged as follows:
Pumped 25 sac cement with drill pipe at 3985'. Pumped 20 sac @ 3566', 20 sac at 1870', and 20 sacks @ 270'. Set marker in 10 sac plug at surface.
Plugged and Abandoned.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____

(Company)

OIL CONSERVATION COMMISSION

Name John W. Runyan
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Vilas Sheldon
Position Partner
Company RESLER AND SHELDON