

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY RESLER & SHELDON 302 Carper Building, Artesia, New Mexico
(Address)

LEASE Phillips State WELL NO. B-1 UNIT L S 28 T 21S R 35E

DATE WORK PERFORMED Jan. 28, 1958 POOL San Simon

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Drilled 12 1/2" hole to 268'. Set 8 5/8" @ 268' w/200 sacks. Circulated to cellar.
After 24 hours tested before drilling plug for 30" w/1000 psi pump pressure. Held OK.
Drilled plug and tested w/1000 psi. Held OK. Resumed drilling.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name *Robert H. Hargrave*

Name *Mary Anna Blanton*

Title _____

Position Sheldon's Secretary

Date _____

Company RESLER & SHELDON