

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company HEIACO Inc.		Address P. O. Box 352, Midland, Texas					
Lease St. N.M. "B" NAT-5	Well No. 3	Unit Letter E	Section 29	Township 21 - S	Range 35 - E		
Date Work Performed November 8, 1959	Pool Wilson	County Leon					

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☒ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☐ Remedial Work



Detailed account of work done, nature and quantity of materials used, and results obtained.

TD - 222'

Spudded 12 1/4" hole 10:00 P.M., November 5, 1959.

Run 211' of 8 5/8" O.D. casing and cemented at 222' with 225 sz. Plug at 191'.
Cement did not circulate. Spot 50 sz. down side of casing, complete fill up.
Job complete 7:30 A.M., November 6, 1959.

Tested 8 5/8" O.D. casing with 600 PSI for 30 minutes from 4:45 P.M. to 5:15 A.M.
November 8, 1959. Tested O.K. Drilled cement plug and re-tested for 30 minutes
from 7:45 to 8:15 A.M., November 8, 1959. Tested O.K. Job complete 8:15 A.M.,
November 8, 1959.

Witnessed by		Position		Company		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	T D	P B T D		Producing Interval	Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter	Oil String Depth	
Perforated Interval(s)						
Open Hole Interval			Producing Formation(s)			
RESULTS OF WORKOVER						
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.		
Approved by 				Name 		
Title				Position Assistant District Superintendent		
Date 11-10-59				Company HEIACO Inc.		