NUMBER OF CO	DISTRIBUTION											
BANYA FF       FILE       U.S.G.S.		N	NEW MEXICO OIL CONSERVATION COMMISSION FORM C-103 (Rev 3-55)									
							OUS REPORTS ON WELLS					
PROMATION OFFICE (Submit to appropriate District Office as per Commission Rule 1106)												
Name of Com		-//w	7-2;			Addres						
HUMBL Lease	E OIL & F	ENG COMPANY					7, Hobbs, New Mexico n Township Range					
Liew M	exico Ste	te B.	I	1		<u>n</u>	32	<u> </u>		1	<b>I−35−</b> E	
Date Work Pe			Pool	-				County				
3=17, 6=23=61 San Simon Lea THIS IS A REPORT OF: (Check appropriate block)												
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):												
Plugging Remedial W						*Attempt to complete.						
Detailed acco	ount of work d	lone, na	ture and quantity	of materials	used, a	and res	ults obta	ined.				
Witnessed by			5. B. Carlson Fill in Bei	OW FOR R		IAL W	ORK RI		OIL & REF	INIA	G COMPANY	
		1			NAL W	ELL D	ATA					
D F Elev. T D		TD		PBTD	PBTD			Producing Interval			Completion Date	
Tubing Diame	Tubing Diameter		Tubing Depth		Oil String Dian			ter	Oil Strin	g Dep	th	
Perforated Int	erval(s)		I	· · · · · · ,	I						······	
Open Hole Interval						Producing Formation(s)						
	······		·····	RESULI	TS OF	WORK	OVER					
Test	Date of Test	f	Oil Production BPD		Producti CFPD		Water Production BPD		GOR Cubic feet/Bbl		Gas Well Potential MCFPD	
Before Workover	· · · · · · · · · · · · · · · · · · ·											
After Workover												
						I hereby certify that the information given above is true and complete to the best of my knowledge.						
Approved by Leslie A. Clement						Name (right DEsty						
/						Position Agent						
Date						Compa		LE OIL &	REFINING	COMF	ANY	

Humble Oil & Refining Company Box 2347 Hobbs, New Mexico

New Mexico State BJ, Well #1, Unit D, Section 32, T-21-S, R-35-E, Lea County, New Mexico.

Perforated 2-7/8" csg from 3829 to 3833, 3840-3843, 3848-3850, 3857-3861, with 2 shots per foot. Fraced perforations from 3829-3861 with 15,000 gal Humble Frac and 30,000# sand, average injection rate 8.1 BPM. Swabbed and flowed 22% hours, recovered 271 bbls load oil and 129 bbls water. Set CI Bridge Plug at 3818. Perforated 2-7/8" csg from 3790-3800 with 2 shots per foot, acidized per from 3790-3800 with 15,000 gal Humble Frac and 30,000# sand. Average injection rate 10.5 BPM. Swabbed and flowed 80 hrs, recovered 324 bbls load oil and 80 bbls water. Pumped 377 hours, recovered 134 bbls load oil and 153 bbls water. Pushed Bridge Plug to 3873. Run tubing and rods, produce through perforations from 3790-3861. Pumped 270 hours, rec 16 bbls oil, 105 bbls water. Pulled tubing and rods. Set cmt plug from 3873-2450 with 85 sacks (35 sacks went into formation), set plug from 100-0 with 10 sacks. Well plugged and abandoned.

Installed marker as required by NMOCC.

C-103 will be forwarded when location is cleaned and leveled.