

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY RESLER & SHELDON 302 Carper Building, Artesia, New Mexico
(Address)

LEASE Phillips State "C" WELL NO. 2 UNIT H S 32 T21 South R 35 East
DATE WORK PERFORMED May 15, 1958 POOL San Simon

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.
Drilled to 265' in 11" hole. Set 8 5/8" on bottom and cemented with 200 sack cement.
Let stand 24 hours then tested 1000 psi. Held for 30 minutes, drilled out and again tested
for 30 minutes at 1000 psi. Held OK so drilled ahead.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:
DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
	(Company)	

OIL CONSERVATION COMMISSION	I hereby certify that the information given above is true and complete to the best of my knowledge.
Name <u>[Signature]</u>	Name <u>Wes Sheldon</u>
Title <u>Inspector</u>	Position _____
Date <u>May 15, 1958</u>	Company <u>RESLER & SHELDON</u>