

DAILY OPERATIONS REPORT

DATE 11/12/97 HOURS ENDING _____ AM/PM

FIELD Eunice Mex. South Unit AFE NO. _____

LEASE EMSU AUTHORIZED \$ _____

WELL NO. 259 DAILY COST \$ _____

RIG # 660 CUMULATIVE \$ _____

SUPERVISOR Duncan

OIL RECOVERED _____ BLWTR _____

WATER RECOVERED _____ BLOT _____

BRIEF JOB DESCRIPTION Repair Pkr./Hq. leak.

NARRATIVE: M.I. R.U. Pucio Unit. Top joint
parted on injection pipe. R.I.H. w/ fishing
tool & fished parted + hq. P.O.H. w/ hq & pkr.
R.I.H. w/ Guiberson G-6 pkr, ON & OFF tool
and 1.78" profile nipple. Set pkr. @ 3653'. w/
10,000# compression. Tested Annulus to 550#
tested okay. R.D. unit & started well
injecting produced fluid.