



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Alamos
Lease No. 13 02170 (b)
Unit N.M.S.U.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Subsequent Report of Casing Repair</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

A. H. Meyer B-4 No. 3 Alamo, New Mexico June 30, 19 55

Well No. 3 is located 3970 ft. from N line and 300 ft. from E line of sec. 4
Lot 16, Section 4 203 363 N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Alamo Ala New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The subject well was pumping 11 bbls. oil, 25 bbls. water in 24 hours. F.O. 3670'. Dayburg pay 3612-3670'. Open hole 3716-3670'.
 In repairing casing the following work was performed: Set bridging plug at 3675'. Found holes in casing at 448' and 930'. Square cemented holes in 5 1/2" casing at 448' and 930' with 400 sacks cement. Pressure 400# to 450#. Cement circulated out of 7 5/8" casing, squeezed out 150 sacks. Drilled out plug and tested 5 1/2" casing with 1200#. Tested okay. Drilled out bridging plug at 3675' and pushed plug to bottom.
 The well then pumped 14 bbls. oil, 3 bbls. water in 24 hours.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company
 Address Box 427
Alamo, New Mexico
 By [Signature]
 Title District Superintendent