


(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	1
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Weyer 3-4 No. 6

Hobbs, New Mexico

April 5, 1951

Well No. 6 is located 3300 ft. from EX line and 1960 ft. from W line of sec. 4

SW/4 Sec. 4
(1/4 Sec. and Sec. No.)

21-8
(Twp.)

36-8
(Range)

N.H.P.M.
(Meridian)

Burice
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3577 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 3-19-51, acidized the subject well with 1500 gals. from 3782 to 3864'. After treatment the well failed to flow. After being shut in for seven days recovered 13 bbls. oil and no water in 7 hrs. No further production recovered either by snub or flow.

Before work was performed the subject well had ceased to produce oil. Since treatment the well is dead and has been shut in.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 50

Hobbs, New Mexico

By R. J. Jacob

Title Asst. District Superintendent

