



ST-
SUBJECT TO REVIEW
IN 90 DAYS
(SUBMIT IN TRIPLICATE)
HOURS OFF UNITED STATES
DEPARTMENT OF THE INTERIOR
1962 DEC 4 GEOLOGICAL SURVEY

HOBBS

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Las Cruces
Lease No. 031740 b
Unit Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		X
NOTICE OF INTENTION TO CHANGE PLANS		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		
NOTICE OF INTENTION TO PULL OR ALTER CASING		
NOTICE OF INTENTION TO ABANDON WELL		
SUBSEQUENT REPORT OF WATER SHUT-OFF		
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
SUBSEQUENT REPORT OF ALTERING CASING		
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
SUBSEQUENT REPORT OF ABANDONMENT		
SUPPLEMENTARY WELL HISTORY		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 1, 1962

Well No. 23 is located 660 ft. from N line and 1980 ft. from E line of sec. 4

SW/4 35/4 Sec. 4 21-S 36-E N10°M
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Oil Center Blinbry Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3594 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 6396' 5 1/2" OD 14# & 15.5# csg at 6350' with 720 sacks cement. WOC 36 hours.
Top of cement by temperature survey at 3000'. Thirty minute casing test
before and after drilling plug - 1,000#. Tested OK.

Does Not Cover Yates 2672-3000'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Sunice, New Mexico

USGS-4 INOC-2 NAM File

By

Title District Superintendent