

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2139

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company	8. Farm or Lease Name State H
3. Address of Operator Box 1610, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER 0 FEET FROM THE 3300 South LINE AND 1980 FEET FROM East 5 TOWNSHIP 21S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Eunice Monument
15. Elevation (Show whether DF, RT, GR, etc.) 3597 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Deeper

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

7-22-86: RU PU. POH w/CA. Set pkr @ 3615'. Test Mod "D" pkr @ 3731 to 500#.
 7-23-86: Pmpd into perf 3398-3586' @ 4 BPM.
 7-24-86: Sqz perf w/267 sx Cl "H".
 7-25,26,27-86: DO cmt. Test csg to 500#.
 7-28-86: Reqz w/125 sx Cl "H".
 7-29-86: DO cmt. Test csg to 500# ok. Test witnessed by Chevron.
 7-30-86: Tag cmt @ 3680'. DO cmt to 3716'. Retrieve DR plug. Unable to retrieve pkr w/pkr picker.
 7-31-86: Attempt to mill over pkr. Pkr fell to 3744'.
 8-1-86: Attempt to mill over pkr. Pkr fell to 3899'. RIH w/bit. DO f/3899-3902'. Cleaned out to TD 3910'.
 8-4-86: RIH w/115 jts. 2-3/8" tbg. RD PU. Turn over to Chevron for completion. Will be the Eunice Monument South Unit #226.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

915-688-5672

SIGNED Ken W. Gosnell TITLE Engr. Tech. Spec. DATE 8-6-86

ORIGINAL SIGNED BY JERRY FEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 11 1986

CONDITIONS OF APPROVAL, IF ANY:

7 A S... + (2.00) 5