Submit 3 Copies to Appropriate

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88241-1980 P.O. Box 2088 30-025-04520 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE X FEE 🗌 DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: EUNICE MONUMENT SOUTH UNIT OIL WELL OTHER WIW 2. Name of Operator 8. Well No. Chevron U.S.A. Inc. 251 3. Address of Operator 9. Pool name or Wildcat P.O. Box 1150, Midland, TX 79702 EUNICE MONUMENT; GRAYBURG-SAN ANDRES 4. Well Location 660 SOUTH 1980 Unit Letter Feet From The Line and Feet From The Line 21S 36E Section LEA Township Range **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CHANGE PLANS TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB SQUEEZED OPEN HOLE OTHER: . OTHER: _ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. POH W/INJ EQPT. DUMPED 5200# FRAC SAND; REVERSED OUT EXCESS SAND. SET CICR @ 3759'; COULD NOT PRESSURE. DRILLED CICR & PUSHED TO 3864'. CIRC HOLE CLEAN. SET CICR @ 3697'; TESTED ANN TO 500#-OK. PUMPED 125 SX CL "C"; ALL CMT IN TBG COMM BETWEEN TBG & CSG. REVERSED OUT 40 SX CMT; 75 SX IN FORM, 10 SX IN CSG. TSTD CSG 500#, BLED DN TO 450# & HELD. TAG CMT @ 3637': DRLD CMT, CICR, CMT TO 3865'. CLEANED OUT SAND TO 4059', CIRC HOLE CLEAN. RIH W/INJ EQPT. TESTED PKR & CSG W/CHART. RETURNED WELL TO INJECTION. WORK PERFORMED 1/30/97 - 2/6/97 I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE TECHNICAL ASSISTANT 2/25/97 DATE TYPE OR PRINT NAME TELEPHONE NO. (915)687-7148 (This space for State Use) A COMMENT OF STRY SEXTON FEB 27 1997

TITLE