

HUMBLE OIL & REFINING COMPANY'S

A. J. Adkins No. 2

SW 1/4, Section 10, T 21 South,  
Range 36 East, Lea County,  
New Mexico

DEVIATION SURVEYS

Cyfo test at 915'	-	hole straight
"	"	" 1500' - Deviation $1\frac{1}{2}$ degrees
"	"	" 1920 - " 1 "
"	"	" 2000 - " $1\frac{1}{2}$ "
"	"	" 2100 - " 4 "
"	"	" 2430 - " $4\frac{1}{2}$ "
"	"	" 2572 - " $4\frac{1}{2}$ "
"	"	" 2640 - " $4\frac{1}{2}$ "
"	"	" 2700 - " $4\frac{1}{2}$ "
"	"	" 2800 - " 5 "
"	"	" 2916 - " 5 "
"	"	" 3080 - " 5 "