

HUMBLE OIL & REFINING COMPANY'S

A. J. Adkins No. 2

NW 1/4, Section 10, T 21 South,  
Range 36 East, Lee County, New  
Mexico.

DEVIATION SURVEYS

|                    |   |                    |
|--------------------|---|--------------------|
| Drift test at 100' | - | hole straight.     |
| " " " 225'         | - | " "                |
| " " " 1000'        | - | Deviation 1 degree |
| " " " 1260'        | - | " 2 degrees        |
| " " " 1500'        | - | " 2 1/2 "          |
| " " " 1752'        | - | " 3 "              |
| " " " 2206'        | - | " 3 1/2 "          |
| " " " 2700'        | - | " 3 "              |

DRILL STEM TESTS

None.