


HAMBLE OIL AND REFINING COMPANY MULTI-POINT BACK PRESSURE TEST FOR GAS WELLS

Well Knox 1
Location J-10-21S-36E
County Lea
Date 6-18 to 6-22, 1956



Test number 1, poor point alignment. See test number 2.

Q - MCFD - 15.025 PSIA