

COPY

HUMBLE OIL & REFINING COMPANY  
HOUSTON, TEXAS

## HUMBLE OIL &amp; REFINING COMPANY'S

John D. Knox #1

SE-1/4 of Section 10, Township 21-  
South, Range 36-East, Eunice, N. M.DEVIATION      SURVEYS

Syfo test at	241' - hole straight
Syfo test at	504' - deviation 1/2 of 1 degree
Syfo test at	800' - hole straight
Syfo test at	1000' - deviation 1/2 of 1 degree
Syfo test at	1250' - hole straight
Syfo test at	1500' - deviation 1 degree
Syfo test at	2000' - deviation 3 degrees
Syfo test at	2130' - deviation 4-1/2 degrees
Syfo test at	2500' - deviation 4-1/2 degrees

No drill stem tests were made. Well was swabbed in through  
2" tubing and flowed first hour at rate of 9 barrels per hour.

COPY

HUMBLE OIL & REFINING COMPANY  
HOUSTON, TEXAS

Information for the following is being furnished:

John A. Jones

2-1/4 of Section 10, Township 21-  
North, Range 30-East, T. 21. N.

Production Data

251' - hole straining	to test at
304' - deviation 1 1/2 of 1 degree	to test at
300' - hole straining	to test at
1000' - deviation 1 1/2 of 1 degree	to test at
1350' - hole straining	to test at
1800' - deviation 1 degree	to test at
2000' - deviation 2 degrees	to test at
2150' - deviation 4-1/2 degrees	to test at
2300' - deviation 4-1/2 degrees	to test at

Production data was obtained from all wells completed in this field. The flow rate was 10 to 15 barrels per hour.