

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103
Revised 1-1-89

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	30-025-04662
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	EUNICE MONUMENT SOUTH UNIT
8. Well No.	362
9. Pool name or Wildcat	EUNICE MONUMENT/GB-SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3591 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL ☐ GAS ☐ OTHER Injection
WELL ☒ WELL ☐ OTHER ☐

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location
Unit Letter B : 660 Feet From The NORTH Line and 1980 Feet From The EAST Line
Section 16 Township 21S Range 36E NMPM LEA County

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>REPAIR CASING LEAK</u>	<input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 10-27 THRU 10-29-92
RIH W/ PKR & RBP ON WS & TST CSG 3646-1211, ALL OK.
GIH W/TENSION PKR & TST CSG 1211-SURF, ALL CSG GOOD. DUG UP WELL HEAD
7" CSG HAD TWO RISERS, COMMUNICATION WAS BETWEEN 2 RISERS. BULL PLUGGED
THE BOTTOM RISER, RETRIEVE RBP, GIH W/BIT & TAG @ 3950, NO FILL.
CIRC HOLE W/PKR FLU, TST CSG TO 325# F/30 MIN, LOST 5#, OK. TEST TBG TO 1500#, OK.
THEN PMP OUT THE PLUG @ 2300#.
RETURN WELL TO INJECTION

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 10/30/92

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY Paul Kautz TITLE Geologist DATE NOV 06 '92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
NOV 05 1992
OCD HOBBS OFFICE