

**Budget Bureau No. 42-R358.4.**  
**Form Approved.**

JUL 17 1963

**(SUBMIT IN TRIPLICATE)**

J. L. GORDON

ACTING DISTRICT DEPT

UNITED STATES

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**Las Cruces**

Lease No. 032099 &

Unit \_\_\_\_\_

			A
	X		

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Lockhart A-18**

June 6, 1963

Well No. 5 is located 330 ft. from ~~XXX~~ S line and 2310 ft. from ~~XXX~~ W line of sec. 18

SE/4 SW/4 Sec. 18

21-3

36-E

**NM PM**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

**MMFTU**

**Lee**

## New Mexico

(Field)

(County or Subdivision)

-----  
(State or Territory)

The elevation of the derrick floor above sea level is 3628 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 3935, PB 3840, DF 10, Elev 3628, Csg Pt 5-1/2" at 3792. Pay Queen 3792-3840. Open hole 3792-3840. Well was shut-in incapable of commercial production. Plugging was accomplished in the following manner: Set a 20 sack cement plug from 3700-3540. Set a 10 sack cement plug at surface. Filled intervals between cement plugs with 10 lb. mud. Erected 4" marker extending 4' above surface with well name and location inscribed thereon. Location restored to original condition. Plugging started 5-27-63, comp 5-28-63. All casing was left in the hole.

**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company Continental Oil Company

Address Box 68

Bunice, New Mexico

By \_\_\_\_\_

USGS-5 NMOC-3 ABS File

Title District Superintendent

Pan Am-Mbs-3 Atl-Rosw-2  
Calif Oil-Hous. Mid-1 each