

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

RECEIVED
JAN 2 - 1941
RECEIVED

MISCELLANEOUS REPORTS ON WELL

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within 10 days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

Midland, Texas

December 31, 1940

OIL CONSERVATION COMMISSION
Santa Fe, New Mexico.
Gentlemen:

Place

Date

Following is a report on the work done and the results obtained under the heading noted above at the
Humble Oil & Refining Company New Mexico State "G"

Company or Operator **NW/4 of NW/4** Well No. **36-E** in the
of Sec. **23**, T. **21-S**, R. **36-E**, N. M. P. M.,
Eunice Field, **Dea** County

The dates of this work were as follows: **December 20th to 30th, 1940**

Notice of intention to do the work was ~~(was not)~~ submitted on Form C-102 on **December 10,** 19 **40**
and approval of the proposed plan was ~~(was not)~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Pulled 3839' 3" of 2" tubing. Plugged hole back into 5 1/2" casing 3690' to 3400' with 30 sax El Toro Cement. Shot 5 1/2" casing at 2980', 2860', 2740', and 2620'. Recovered 2599' 8" of 5 1/2" casing leaving 1160' 4" in hole. Filled hole with mud laden fluid to 1450'. Cemented back into 7-5/8" casing 1450' to 1400' with 15 sax El Toro. Shot 7-5/8" casing at 700', 600', and 500', recovering 497' 11". Left 947' 11" in hole. Could not pull 10-3/4" casing, leaving 196' in hole. Circulated hole and filled to bottom of 10-3/4" casing with mud laden fluid. Cemented 10-3/4" casing 211' to 181' with 15 sax El Toro cement. Filled balance of hole to top with mud laden fluid. Cemented top of 10-3/4" casing and erected regulation marker with 15 sax El Toro cement. Work performed by Lea County Casing Pullers. Work supervised by H. S. McGarry, Supt of Humble Oil & Refg. Co, Hobbs, New Mexico.

Witnessed by

No witnesses required.

Company

Title

Subscribed and sworn to before me this
31st day of **December**, 19 **40**

Walter Nae Lugo
Notary Public

My Commission expires **6-1-41**

I hereby swear or affirm that the information given above is true and correct.

Name *Alfonso*

Position **Division Superintendent**

Representing **Humble Oil & Refining Company**

Company or Operator

Address **Box 1600 - Midland, Texas**

Remarks:

Roy Yarbrough
Name
OIL & GAS INSPECTOR

Title