

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

HOBBS OFFICE OCC

Name of Company Continental Oil Company		Address Box 107, Hobbs, Lea, New Mexico				
Lease Lockhart 9-28	Well No. 2	Unit Letter E	Section 28	Township 21	Range 36	
Date Work Performed 6-13-55	Pool Junico			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

In repairing casing the following work was performed: Set bridging plug at 3700'. Found leaks in 5 1/2 casing at 424' and 454'. Squeezed with 450 sacks cement. In testing casing, found another leak at 47' down. Squeezed with 41 sacks cement. Drilled out cement to 460', testing casing with 1,000 psi. Drilled out bridging plug at 37.5' and cleaned out to TD 3939'. Acidized hole with 500 gals. 15% acid. Recovered fluid load.

Witnessed by B. K. Rampley	Position Prod. Foreman	Company Continental Oil Company
--------------------------------------	----------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. 3629	TD 3930	P BTD	Producing Interval 3655-3930	Completion Date 12-13-36
Tubing Diameter 2 1/2	Tubing Depth 3920	Oil String Diameter 5 1/2	Oil String Depth 3833	

Perforated Interval(s)

Open Hole Interval 3633-3930	Producing Formation(s) Grayburg
--	---

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	5-25-55	39		0		
After Workover	6-17-55	48		233		

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by	Name
Title	Position District Superintendent
Date	Company Continental Oil Company