

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease |
| State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. |
| B-1330 |

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|--------------------------------|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator | 8. Farm or Lease Name |
| Skelly Oil Company | State "C" Com. |
| 3. Address of Operator | 9. Well No. |
| P. O. Box 1351, Midland, Texas 79701 | 1 |
| 4. Location of Well | 10. Field and Pool, or Wildcat |
| UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM | Eumont (Gas) |
| THE West LINE, SECTION 29 TOWNSHIP 21S RANGE 36E NMPM. | |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| 3649' DF | Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | |
| | | OTHER Casing Connections <input checked="" type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Riser on 15-1/2" OD and 9" OD Casing brought to surface.
Riser on 9" OD and 7" OD Casing brought to surface.
Inspected by Nathan E. Clegg on May 4, 1976.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | | |
|---------------------------------|---|-------------------------|--------------------|
| (Signed) D. R. Crow | D. R. Crow | TITLE Lead Clerk | DATE 5-7-76 |
| APPROVED BY | Orig. Signed by Jerry Serrano Dist 1, Super. | TITLE | DATE |
| CONDITIONS OF APPROVAL, IF ANY: | | | |