

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease or permit No. 032099-B

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Lockhard B-30# 1

September 8, 1943

Well No. 1 is located 660 ft. from N line and 1980 ft. from W line of sec. 30
SE/4 SW/4 Sec. 30 21-S 36-E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Eunice Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3635 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A cement plug was set from T.D. 3936' to bottom of 5 1/2" casing set at 3788'. Casing was shot off and recovered 2437'3" of 5 1/2" casing. Plugged back inside of 5 1/2" casing with 12# mud and set a cement plug at the top of the 5 1/2" casing left in hole.

Then plugged back to the bottom of the 7 5/8" casing set at 1628' with 12# mud and set a cement plug at the bottom of this casing. 7 5/8" casing was shot off and recovered 591'6" of this casing. Plugged back inside this casing with 12# mud to the bottom of the 10 3/4" casing set at 283' and then plugged back to the surface with cement. A marker was erected and location was restored to its original condition.

cc: CGS-NMOCC

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box CC

Hobbs, New Mexico

By _____

Title Dist. Supt.