

NO. OF COPIES RECEIVED	
DISTRIBUTION	
AMT. FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR NOTICES TO DRILL OR TO REPER OR PLUG BACK TO A DIFFERENT RESERVOIR. SEE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No. -
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		7. Unit Agreement of Name -
2. Name of Operator TEXACO Inc.		8. Firm or Lease Name J. K. Rector
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico 88240		9. Well No. 5
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 21-S RANGE 36-E N.M.P.M.		10. Field and Pool, or Wellbore Eumont Seven Rivers Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3635' (DF)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER ☒ Addl. perfs in Eumont

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Pull rods, pump & tubing. Install BOP.
2. Clean out to 3915' (PBTD).
3. Perforate 4-1/2" csg w/2 JSPF @ 3627', 34', 43', 52', 62', 70', 80', 88', 3705', 09', 26', 34', 65', 84', 95', 3801', 09', 15' & 3823'.
4. Set pkr @ 3755', acidize perfs. 3765-3896' w/6000 gals. 15% DS-30 Acid in 3-1000 gal. & 6-500 gal. stages using 700# salt & 400# Benzoic acid flakes after 1000 stages & 20 Ball Sealers after 500 gal. stages. Flush w/20 Bbls. KCC water.
5. Set RBP @ 3755' & pkr @ 3506'. Acidize perforations 3627-3734' w/4000 gals. 15% DS-30 in 4 equal stages using 30 Ball Sealers. Flush w/15 Bbls. KCL water.
6. Install pumping equipment and test.
7. Workover unsuccessful. Well shut in (Classified TR-0, To Recondition-Oil). Held for further study, 8-10-78.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Jerry Sexton* TITLE Asst. District Supt. DATE 8-17-78

APPROVED BY *Dan L. Sapp* TITLE Expires 8/21/79 DATE

CONDITIONS OF APPROVAL, IF ANY