


Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 065525

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON ~~WELLS~~ ^{WELL}

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....		
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....		
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

11-21, 19 51

Elliott
Well No. 1 is located 660 ft. from XXX line and 660 ft. from XXX line of sec. 1
SW 1/4 Sec. 1 T-21-S R-37-E N M P M
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3494 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-12" casing was set at 8333' and cemented on 11-17-51 and after letting cement set for 72 hours, found top of cement at 8210', applied 1025# pressure for 45 minutes, pressure increased to 1040#, drilled to 8334' (1' below shoe) applied 1035# for 45 minutes, no drop in pressure. Drilling was resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Fullerton Oil Company

Address P. O. Box 2227

Hobbs, New Mexico

By D. W. Fenigan
Title Office Manager